






**FIG. 2**




JAN 09 2004

3/14

**FIG. 3**

**Highly Cracked or  
Completely  
Broken Off Blade**





## Replacement Sheet

App. No.: 09/930,104


Docket No.: 02640/100G826-US1

Inventor: Allan L. Friedman et al.

**Title: METHOD FOR DIFFERENTIATING BETWEEN GUNKED AND CRACKED ULTRASONICALLY TUNED BLADE**

4/14

FIG. 4





Replacement Sheet

App No.: 09/930,104


Docket No.: 02640/100G826-US1

Inventor: Allan L. Friedman et al.

Title: METHOD FOR DIFFERENTIATING BETWEEN GUNKED  
AND CRACKED ULTRASONICALLY TUNED BLADE


5/14

**FIG. 5**




6/14

**FIG. 6a**





7/14

**FIG. 6b**



Replacement Sheet

App No.: 09/930,104


Docket No.: 02640/100G826-US1

Inventor: Allan L. Friedman et al.

Title: METHOD FOR DIFFERENTIATING BETWEEN GUNKED  
AND CRACKED ULTRASONICALLY TUNED BLADE

8/14


## FIG. 7(a)






9/14

## FIG. 7(b)






10/14

**FIG. 8(a)**



11/14


**FIG. 8(b)**





12/14


## FIG. 9





13/14

## FIG. 10



JAN 09 2004

14/14

**FIG. 11**

